

I have carried out a survey of the following footpaths in completion of the Oct/Nov monitoring of the public rights of way in this parish. The results of the inspection carried out on the 25th Oct, 6th 7th 10th 13th and 14th Nov.

FP1 - North Burlingham/Burlingham Green

Path and signs satisfactory. New Fingerpost at Burlingham Green as requested last report. During inspection - encroaching bramble cut back

FP2 - Old Dairy Farm/Belt Plantation (now part of Burlingham Woodland Walks)

Path and signs satisfactory

FP3 - Church Rd/A47

Path and signs satisfactory

FP4 - Post Office Rd/Church Rd

Path and signs satisfactory.

FP5 - Pack Lane/Blofield Rd

Path and signs satisfactory.

FP6 - Chapel Rd/Station Rd

Path and signs satisfactory

Waymarker at Station Rd end partially obscured by ivy.

FP7 - Lodge Rd/South Burlingham Rd

Path and signs satisfactory

FP8 - Norwich Rd/parish boundary FP2 Beighton

Path and sign satisfactory

During inspection; encroaching bramble throughout trimmed back.

New Fingerpost at Norwich Rd end. Damaged step of stile removed following problems raised last inspection.

FP9 - Norwich Rd/ Buckenham Rd

Signs satisfactory. Path passable but nettle growth beside path in places requires cutting. During inspection - encroaching bramble cut back

FP10 - Buckenham Rd/parish boundary FP11 Strumpshaw

Path and sign satisfactory

FP11 - Pack Lane

Tree branches obscuring finger post at Chapel Rd end require cutting back.

This concludes the monitoring of the PRW for the period Oct/Nov 2017

Actions I have taken following this inspection:

FP6 - Ivy obscuring way marker cut back.

FP9 - Requested BADCOG to cut nettle

FP 11 - Branches obstructing Fingerpost cut back.

Yours sincerely

Tony Bowyer

Footpath Warden - Lingwood & Burlingham